UI Bulletin #165b

Subject:	Fuel Filler Elbow Assembly `Service Body' Installation
Model Year(s):	2019 and beyond
Models Affected:	Chevrolet Silverado HD Medium Duty (4500/5500/6500)
Origination Date:	March 20, 2020
Revision Date:	N/A

ADVISORY:

Condition/Concern:

This bulletin provides awareness for GM Service Part (pre-formed) 90 degree Fuel Filler Hose Elbows/Clamps Kit specific to Chassis Cab `Service Body' Type Installations. These kits, for use with factory supplied filler hose assembly & straight pipe (upfitter supplied) components complete filler routing requirements for `Service Body' type upfits.

Recommendation:

Per the GM Online Order Guide SEO Option Code `BJA' will include Fuel Filler Hose Elbows/Clamps for Single and Dual tank applications via `bag in cab' when in BJA is ordered with the vehicle. Kit P/Ns, components and illustrations are noted below in figures 1 & 2. Note, these kits are NOT available for order from service parts, however you can obtain the individual pieces using the P/Ns listed below. Figures 3 & 4 show the as built and modified fuel filler routings.

Single Tank Elbow and Clamp required P/Ns



20813414 (1)
20788860 (1)
12338017 (3)

Dual Tank Elbow and Clamp required P/Ns



20813414 (2)
20788860 (2)
12338017 (6)

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.



Figure 3 – Factory Equipped Straight Fill Hose Assembly



Figure 4 - Fuel Filler with Elbow Kit (Purple) installed by Upfitter

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.